


113.794


Running Brush Whirlwind




Tools required:




screwdriver



wire stripper



side cutters



hot glue




soldering iron


NOTE:


After completion, the OPITEC work kits are not articles with toy character of a generally commercial kind, but teaching and learning aids to support educational work. This kit may only be built and operated by children and young people under the guidance and supervision of competent adults. Not suitable for children under 36 months. Danger of suffocation!

Parts list	Quantity	Dimensions (mm)	Designation	Part no.
brush head	1	ø40	brush	1
battery holder	1			2
pressure switch with lugs	1		switch	3
motor	1		drive	4
lustre terminal insert	1		unbalanced weight	5
screw	2	M3x8	attachment unbalance	6

Instructions 113.794
Running Brush Whirlwind







Instructions 113.794
Running Brush Whirlwind

